

MICHELIN CONDOR TIRE

UNWAVERING PERFORMANCE. UNBEATABLE VALUE.



Michelin Condor aircraft tires offer outstanding durability and value, which explains why they've been popular with flight schools for so many years. They are tough enough to handle the rigors of a flight school environment and available at an economical price, all while offering peace of mind. For tires that deliver quality, reliability and high value, contact your Michelin aircraft tire dealer today.

aircraft.michelin.com



MICHELIN CONDOR TIRE

TOUGH TIRES. GREAT VALUE.

Exceptional Stability

Provided by strong side walls, even after frequent hard landings.

Long Tire Life

Tough tread for high abrasion resistance and low heat generation.

Economical

Excellent durability for the money.

Peace of Mind

Unwavering performance when you need it most.

Typical Construction



Size	Ply Rating	Speed (MPH)	Part Number	Avg. Wgt. (lbs.)
5.00-5	4	120	072-308-0	5.8
5.00-5	6	120	072-312-0	5.8
6.00-6	4	120	072-315-0	9.1
6.00-6	6	120	072-314-0	9.1
6.00-6	8	120	072-317-0	9.1
6.50-8	8	120	072-364-0	13.1
6.50-10	8	120	078-345-0	16.0
6.50-10	10	120	078-356-0	16.0

Size	Ply Rating	Speed (MPH)	Part Number	Avg. Wgt. (lbs.)
7.00-6	6	120	072-313-0	11.0
7.00-6	8	120	072-306-0	11.0
8.00-6	6	120	072-371-0	12.7
8.00-6	8	120	072-374-0	12.7
8.50-10	8	120	072-376-0	24.0
8.50-10	10	120	072-379-0	24.0
15X6.0-6	6	120	072-449-0	7.2
29X11.0-10	10	160	078-446-1	31.0

MICHELIN AIRCRAFT SALES OFFICE LOCATIONS

North, Central & South America Michelin North America, Inc.

One Parkway South
Greenville, SC 29615 USA
Phone: +1-877-503-8071

Europe, CIS, Middle East & Africa Manufacture Francaise Des Pneumatiques Michelin

23, Place des Carmes-Déchaux
63040 Clermont-Ferrand Cedex 9 FRANCE
Phone: +33 (0) 4 73 30 14 85

Asia and Oceania Michelin Siam Co., Ltd.

33/4 Rama 9 Road, Huay Kwang Sub-district,
Huay Kwang District, Bangkok 10310, THAILAND
Phone: +662-700-3000

aircraft.michelin.com

All Michelin Condor tires are tube-type, and rated at either 120 MPH or 160 MPH (see above). Operator should confirm correct tire size with the original aircraft manufacturer. All specifications are subject to change without notice. | Copyright © 2024, Michelin North America, Inc. All rights reserved.

